

**AKAI**  
*professional*

**S5000/S6000**

**STEREO DIGITAL SAMPLER**  
**Software Version 1.10 Addendum**

**WARNING**

To prevent fire or shock hazard, do not  
expose this appliance to rain or moisture.

**Operator's Manual**

# AKAI

*professional*

Version 1.10a of the S5000 and S6000 Operating System fixes many known and serious problems as listed below.


## GENERAL

- Support for ISO9660 and Joliet encoded CD-ROM format.
- General improvement of voice handling/MIDI timing. Note-on times are now appreciably faster and overall timing is now considerably better. There is also less likelihood for erroneous voice stealing.
- General overall improvements to disk system, especially SAVE.
- General improvements to overall stability and reliability.
- General improvements to sound library compatibility (in particular with S1000 material).

## BUGS FIXED IN V1.10a

- Digital output has incorrect status bits
- Upper and lower case should be recognised as the same letter when saving.
- Pressing CLOSE FOLDER on a folder that is already closed causes crash in Load page.
- Loops are not imported correctly from 3rd Party PC/Mac sample editors such as SoundForge, D-SoundPro, etc..

*NOTE: When trimming the end point of a looped sample, 15 sample points are required between the loop end and the sample end.*



*The S5/6000 takes this requirement into consideration when setting either the loop end or sample end but 3rd party wave editors do not. Please do not trim the sample end too close to the loop end when using such wave editors.*



**BUGS FIXED (cont.)**

- After disk format, previous disk contents still shown.
- Velocity switching problems - this is not due to problems with velocity switching as such but due to other parameters (such as filter envelope depth) not being read correctly thereby giving the impression that velocity switching isn't working properly.
- Disk is corrupted after root directory limit is reached.
- Attempt to audition from 8bit sample in LOAD causes disk lock.
- Cannot recover RAM space after delete or purge.
- Cannot delete folder - prompts you that it contains files even when it doesn't.
- Disk info.is incorrect after editing by PC.
- Stereo samples are randomly phase incoherent.
- Loop is missing when Audition from HD is used.
- Quick operation of Audition sample sometimes causes the sampler to crash.
- If memory holds many samples, entering Loop page causes screen corruption and further operation will cause lock up sometimes.
- Output selection in zones page incorrect with S1000 PRG.
- Can not select FDBACK MONITOR in FX Delay/Echo page.
- When saving OS into Flash, particular procedure stores a corrupt OS causing polyphony to be reduced dramatically.
- Incorrect limitation of files number in a folder.

We are aware that some issues remain unresolved in this release but please be assured that these will be addressed in subsequent upgrades as soon as possible.





















